PCN Number:	20160920001	PCN Date: Sept. 22, 2016						
Title: Datasheet for	SN54HCT245 and SN74HCT245							
Customer Contact:	PCN Manager		Dep	pt: Quality Services				
Change Type:								
Assembly Site	Design		$\square$	Wafe	r Bump Site			
Assembly Process	Data Sheet		H	Wafer Bump Material				
Assembly Materials			H		r Bump Process			
	Mechanical Specification		H		r Fab Site			
Packing/Shipping/			H		r Fab Materials			
			H		r Fab Process			
Notification Details								
Description of Change:								
	orated is announcing an info	rmation only no	otifi	cation	etc.			
Texas Instruments Incorporated is announcing an information only notification etc.								
The product datasheet(s) is being updated as summarized below.								
The following change history provides further details.								
TEXAS INSTRUMENTS			SN54	HCT24	5, SN74HCT245			
INSTRUMENTS					VISED AUGUST 2016			
Changes from Revision E (Aug	ust 2003) to Revision F				Page			
Deleted Ordering Information	, see POA at the end of the datasheet				1			
	ature Description section, Device Function							
section, Power Supply Recon	nmendations section, Layout section, Dev	vice and Documentation	on Su	ipport se	ction, and			
	Orderable Information section							
<ul> <li>Updated values in the Therma</li> </ul>	al Information table				5			
The datasheet number wil	I be changing.							
Device Family	Change From			C	hange To:			
SN54HCT245, SN74HCT2	245 SCLS020E			S	CLS020F			
These changes may be re-	viewed at the datasheet links	s provided.						
http://www.ti.com/produc	<u>t/SN54HCT245</u>							
Reason for Change:								
To accurately represent th	ne device thermal characteris	tics.						
Anticipated impact on I	Fit, Form, Function, Oualit	v or Reliabilit	:v (I	positi	ve / negative):			
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative): No anticipated impact. This is a specification change announcement only. There are no changes to								
the actual device.								
Changes to product identification resulting from this PCN:								
None.								
Product Affected:								

5962-8550601VRA	SN54HCT245J	SN74HCT245DWRE4	SN74HCT245PWLE
5962-8550601VSA	SN74HCT245DBLE	SN74HCT245DWRG4	SN74HCT245PWR
85506012A	SN74HCT245DBR	SN74HCT245N	SN74HCT245PWRE4
8550601RA	SN74HCT245DBRG4	SN74HCT245NE4	SN74HCT245PWRG4
JM38510/65553BRA	SN74HCT245DW	SN74HCT245NSR	SN74HCT245PWT
JM38510/65553BSA	SN74HCT245DWE4	SN74HCT245NSRG4	SNJ54HCT245FK
M38510/65553BRA	SN74HCT245DWG4	SN74HCT245PW	SNJ54HCT245J
M38510/65553BSA	SN74HCT245DWR	SN74HCT245PWG4	SNJ54HCT245W

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com