



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000802

DATE: 17-Jun-2015

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX9644EBS+G45	N/A			Part reactivated from prior notice: M000852I
Reactivation	MAX9644EBS+TG45	N/A			Part reactivated from prior notice: M000798
Lead-Free Conversion	MAX1605EUT	MAX1605EUT+	17-Jun-2015	17-Jun-2015	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS25LV02R+	DS2502R+T&R	17-Dec-2015	17-Dec-2017	The part was not released
Discontinuance	DS25LV02R+T&R	DS2502R+T&R	17-Dec-2015	17-Dec-2017	Part can no longer be manufactured
Discontinuance	DS9072-40V	N/A	17-Jun-2015	17-Jun-2015	Part is leaded. Request information on lead-free version
Discontinuance	DS9072H-40R	N/A	17-Jun-2015	17-Jun-2015	Part is leaded. Request information on lead-free version
Discontinuance	MAX2674EVKIT+	N/A	17-Dec-2015	17-Dec-2017	EVKIT is No Longer Supported
Discontinuance	MAX2674EWT+	N/A	17-Dec-2015	17-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX2674EWT+T	N/A	17-Dec-2015	17-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX9668ETP+	N/A	17-Dec-2015	16-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9668ETP+T	N/A	17-Dec-2015	17-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX9672ETI+	N/A	17-Dec-2015	17-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX9672ETI+T	N/A	17-Dec-2015	17-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX9672ETI+TG0E	N/A	17-Dec-2015	17-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX9674ETI+	N/A	01-Jul-2016	16-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9674ETI+T	N/A	01-Jul-2016	16-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9679AETG+	N/A	17-Dec-2015	17-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX9679BETG+	N/A	17-Dec-2015	16-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9679BETG+T	N/A	17-Dec-2015	16-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9679EVKIT+	N/A	17-Jun-2015	17-Jun-2015	EVKIT is No Longer Supported
Discontinuance	MAX9684AETN+	N/A	15-Dec-2016	16-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9684AETN+T	N/A	15-Dec-2016	16-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9684ETN+	N/A	01-Jul-2016	16-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9684ETN+T	N/A	01-Jul-2016	16-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9684EVKIT#	N/A	17-Jun-2015	17-Jun-2015	EVKIT is No Longer Supported

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2015

Discontinuance	MAX9697ATI+T	N/A	01-Jul-2016	16-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9697ATI+TC92	N/A	01-Jul-2016	16-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9697EVKIT+	N/A	17-Jun-2015	17-Jun-2015	EVKIT is No Longer Supported
Discontinuance	MAX9812HEXT+	MAX9814ETD+	17-Jun-2015	17-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX9812HEXT+T	MAX9814ETD+T	17-Jun-2015	17-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX9812LEVKIT+	MAX9814EVKIT+	17-Jun-2015	17-Jun-2015	EVKIT is No Longer Supported
Discontinuance	MAX9812LEXT+	MAX9814ETD+	17-Jun-2015	17-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX9812LEXT+T	MAX9814ETD+T	17-Jun-2015	17-Dec-2017	Part can no longer be manufactured
Discontinuance	VT8012FQD-A00	N/A	17-Dec-2015	17-Dec-2017	Part is leaded. Request information on lead-free version