




Product Change Notification (PCN)

PCN Number	509406	Date Issued	February 16, 2021
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Special Request		
Assessment of Change	Test report/Specification Test Report		
Internal Molex Qualification Date	February 23, 2021		
Sample Availability Date (Changed Part)	February 23, 2021		
Planned Implementation Date	March 01, 2021		
Method of Identifying Change	Date code		

RELEASED

Before Change


Before



After Change

Overview

- To reduce the occurrence of solder-bridging across the fuses we changed the PCB design and 4 component position. We finished related function testing and reviewed with Ford to get approval.
- No Impact to Fit, Form, or Function.
- Affected Part Numbers
 - 2003161003 (Ford Specific Part Number)
 - 2003161103 (General Market Part Number)
- Qualification Reports and samples available upon request after the date shown above





Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:509406**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com