

## Global Change Notification (GCN)

Product Family	Stacked SSFP 2x4	10654587	
Floudet Failing		10034387	
		GCN Number	
Series	Multiple	September 19, 2014	
		Date Issued	
Reason For Change	New, Modified, Or Replacement Tooling		
Change Description	This letter is to inform you that Molex has added another tool for producing one of the components used to make 2x4 Stacked SFP cages. This is a tool for the component designated as the top cover. This change does not require any changes be made by customers. This tool was added for capacity reasons.		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.		
Reason For Short Notice Exception	New Capacity		
Assessment Of Change (How Product Will Be Qualified & Validated)	Improve capacity		
Internal Molex Qualification Date (Planned Date Information Available)	September 10, 2014		
Sample Availability Date (Changed Part)	September 22, 2014		
Date of Implementation	October 20, 2014		
Method of Identifying Change	Lot traceability		
Recommended Replacement Parts	N/A		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com