BOURNS

Product Change Notification

CPTC RESETTABLE FUSES

March, 2017

Bourns[®] Model CMF-SD Series Ceramic PTC Resettable Fuses *Change to Carrier Tape*

The carrier tape for Bourns[®] Model CMF-SD Ceramic PTC Resettable Fuses is being improved to allow for better pick-and-place operations. The cavity bottom of the new carrier tape is changing from four individual bosses to a single crossed boss. This change will allow the product to sit more level in the carrier tape, thereby improving pick-and-place operations. There is no change to the form, fit, function, quality, or reliability of the CMF-SD product family.



Carrier Tape Before (Four Individual Bosses)

Affected Part Number	Implementation Date of New Carrier Tape	Date Code
CMF-SD10-2	Immediately	-
CMF-SD25-2	Immediately	-
CMF-SD25-10-2	Immediately	-
CMF-SD35-2	Immediately	-
CMF-SD35-10-2	Immediately	-
CMF-SD50-2	Immediately	-
CMF-SD50-10-2	Immediately	-



Carrier Tape After (Single Crossed Boss)

Affected Part Number	Implementation Date of New Carrier Tape	Date Code
CMF-SD25A-10-2	June 1, 2017	1722
CMF-SD35A-2	June 1, 2017	1722
CMF-SD35A-10-2	June 1, 2017	1722
CMF-SD50A-2	June 1, 2017	1722
CMF-SD50A-10-2	June 1, 2017	1722

Due to circumstances beyond Bourns' control, the new carrier tape has been implemented immediately for select part numbers.

If you have any questions or need additional information, please feel free to contact Customer Service/ Inside Sales.