



NO:PX-067PRODUCT:E2A-M08/-S08 Proximity SensorsDATE:March 2015TYPE:Partial Discontinuation Notice

Select E2A-M08/-S08 Inductive Proximity Sensors to be Discontinued; Replace with Similar E2A Models

Last Order Date: May 2015

Note: Date is subject to change based on raw materials and components availability at the factory.

Reason for Discontinuation: Due to a factory change, production of these inductive proximity sensors is being relocated from Europe to China.

Performance specifications stay the same. The housing material is the key difference between discontinued products and their replacements. Brass housing models will be replaced with SUS303 stainless steel housing models.

OC Code	Item description	Comment	Status	OC Code	Item description	Comment
E2A 9838D	E2A-M08KN04-M1-B2	Brass housing	Conditional replacement	E2A 7221M	E2A-S08KN04-M1-B2	SUS303 housing
E2A 9836H	E2A-M08KS02-M1-C2	Brass housing	Conditional replacement	E2A 7235M	E2A-S08KS02-M1-C2	SUS303 housing
E2A 9875R	E2A-M08LN04-M1-C1	Brass housing	Conditional replacement	E2A 7247D	E2A-S08LN04-M1-C1	SUS303 housing
E2A 9876G	E2A-M08LN04-M1-C2	Brass housing	Conditional replacement	E2A 7248B	E2A-S08LN04-M1-C2	SUS303 housing
E2A 9878C	E2A-M08LS02-M1-B2	Brass housing	Direct replacement	E2A 1078R	E2A-M08LS02-M1-B2	SUS303 housing
			Conditional replacement	E2A 7260A	E2A-S08LS02-M1-B2	SUS303 housing
E2A 9879A	E2A-M08LS02-M1-C1	Brass housing	Conditional replacement	E2A 7205R	E2A-S08LS02-M1-C1	SUS303 housing
E2A 9840F	E2A-M08KN04-M1-C2	Brass housing	Conditional replacement	E2A 7222R	E2A-S08KN04-M1-C2	SUS303 housing
E2A 9874M	E2A-M08LN04-M1-B2	Brass housing	Conditional replacement	E2A 7246F	E2A-S08LN04-M1-B2	SUS303 housing
E2A 9880E	E2A-M08LS02-M1-C2	Brass housing	Conditional replacement	E2A 7261M	E2A-S08LS02-M1-C2	SUS303 housing
E2A 9928C	E2A-S08LS03-M5-B1-01	SUS303 housing Long distance	Conditional replacement	E2A37033E	E2A3-S08KS03-M5-B1	SUS303 housing Long distance
E2A 9947M	E2A-S08LS03-M5-C1-01	SUS303 housing Long distance	Conditional replacement	E2A37035A	E2A3-S08KS03-M5-C1	SUS303 housing Long distance

Affected Parts

Reference Documentation

Description	Media	Publication number
E2A datasheet	PDF	D096-E1-01B