

## **Global Change Notification (GCN)**

10716453

		GCN Number	
Series	172677 & 172249	October 01, 2015	
		Date Issued	
Reason For Change	Product Component Change		
Change Description	This letter is being sent to announce that Molex is changing the Solder Rite terminals from a brass alloy to a copper alloy. This change is being made as a part of ongoing product enhancement.		
Series image - Reference only			
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e	e-mail message.	
Reason For Short Notice Exception			
Assessment Of Change (How Product Will Be Qualified & Validated)	The terminals will complete the Molex internal quaprior to their release to production. Reports will b September 2, 2015.		
Internal Molex Qualification Date (Planned Date Information Available)	September 02, 2015		
Sample Availability Date (Changed Part)	September 02, 2015		
Date of Implementation	October 05, 2015		
Method of Identifying Change	Product made after October 5, 2015 will contain t	he new alloy.	
Recommended Replacement Parts	Not applicable		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

SolderRight™

Product Family

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com