

Global Change Notification (GCN)

Product Family	DVI	10725657	
		GCN Number	
Series	74323	November 23, 2015	
		Date Issued	
Reason For Change	Outsourcing Component Or Subcomponent		
Change Description	"This GCN is to change the front shield plating from tin to solderable nickel to avoid the discoloration issue after soldering process. Impacted product series: 74323 DVI plug QI $\#$ is 10724949 "		
Before		After	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.		
Reason For Short Notice Exception	8D Corrective Action Changes		
Assessment Of Change (How Product Will Be Qualified & Validated)	Internal qualification has done.		
Internal Molex Qualification Date (Planned Date Information Available)	October 08, 2015		
Sample Availability Date (Changed Part)			
Date of Implementation	October 25, 2015		
Method of Identifying Change	No special mark		
Recommended Replacement Parts	N/A		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com