

Product Change Notification - SYST-280JFH276

Date:

30 Aug 2019

Product Category:

Memory

Affected CPNs:



Notification subject:

Data Sheet - AT25080B/AT25160B - Complete Datasheet Document Revision

Notification text:

SYST-280JFH276

Microchip has released a new Product Documents for the AT25080B/AT25160B - Complete Datasheet of devices. If you are using one of these devices please read the document located at <u>AT25080B/AT25160B - Complete Datasheet</u>.

Notification Status: Final

Description of Change:

- 1) Updated to the Microchip template. Microchip DS20006244 replaces Atmel document 5228.
- 2) Updated Part Marking Information. Added ESD rating.
- 3) Removed the 8ball WLCSP detail and ordering code.
- 4) Removed lead finish designation.
- 5) Added POR recommendations section.
- 6) Updated trace code format in package markings.
- 7) Updated section content throughout for clarification.
- 8) Updated the 8U31 VFBGA package drawing.
- 9) Updated the SOIC, TSSOP and UDFN package drawings to the Microchip equivalents.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 30 Aug 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A Attachment(s):

AT25080B/AT25160B - Complete Datasheet

Please contact your local <u>Microchip sales office</u> with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our <u>PCN home page</u> select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the <u>PCN FAQ</u> section.

If you wish to <u>change your PCN profile</u>, <u>including opt out</u>, please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and



make the applicable selections.

Affected Catalog Part Numbers (CPN)

AT25080B-WWU11L

AT25080B-WWU11LER

AT25080B-SSHL-B

AT25080B-SSHL-B-899

AT25080B-XHL-B

AT25080B-XHL-B-899

AT25080B-SSHL-T

AT25080B-SSHL-T-899

AT25080B-XHL-T

AT25080B-XHL-T-899

AT25080B-MEHL-T

AT25080B-CUL-T

AT25080B-MAHL-T

AT25080B-MAHL-T-899

AT25080B-MAHL-E

AT25160B-WWU11L

AT25160B-WWU11LER

AT25160B-WWU27LER

AT25160B-SSHL-B

AT25160B-SSHL-B-899

AT25160B-XHL-B

AT25160B-XHL-B-899

AT25160B-SSHL-T

AT25160B-SSHL-T-899

AT25160B-XHL-T

AT25160B-XHL-T-899

AT25160B-XHLHX-T

AT25160B-MEHL-T

AT25160B-CUL-T

AT25160B-MAHL-T

AT25160B-MAHL-T-899

AT25160B-MAHL-E

Date: Thursday, August 29, 2019