

Global Change Notification (GCN)

Product Family	HDAC		10632645	
			GCN Number	
Series	30700 / 30968 / 31389		April 21, 2014	
			Date Issued	
Reason For Change	New, Modified, Or Replacement Tooling			
Change Description	Molex is creating two new molds to increase our capacity to make HDAC assemblies at our Lincoln NE location. One mold will make 30700 24 circuit housings and the other mold will make 30968 24 circuit housings.			
30700 Female - Series image - Reference	only	30968 Male - Serie	es image - Reference only	
Part Numbers Affected	Please refer to Cust	comerPartList.csv attache	d to e-mail message.	
Reason For Short Notice Exception	New Capacity			
Assessment Of Change (How Product Will Be Qualified & Validated)	The capacity tooling and will go through dimensional and product validation testing as part of the qualification. PPAP documentation will be available upon request.			
Internal Molex Qualification Date (Planned Date Information Available)	May 01, 2014			
Sample Availability Date (Changed Part)	May 01, 2014			
Date of Implementation	May 22, 2014			
Method of Identifying Change	HDAC assemblies m	nade after May 1, 2014.		
Recommended Replacement Parts	Not Applicable			
Last Time Buy Date for Obsolete Parts				
Last Time Ship Date for Obsolete Parts				

Contact	Name	E-mail	Phone Number		
Sales Engineer	Please refer to e-mail message for your local sales engineer.				
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416		
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751		
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472		
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352		

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com