

November 13, 2013

Murata Power Solutions hereby gives official notification that the following product(s) are becoming obsolete with immediate effect. Most of the models in the list have negligible historical activity and some items have zero activity.

It is due to material obsolescence that we are unable to support this product. For this reason we are not able to accept new orders and there will be no opportunity for a last time buy.

For the status of any open orders you may have, please contact our local Sales team.

We do not offer alternative equivalents for the models included in the EOL notice. It is recommended that you speak with our local FAE to determine if another model may be appropriate for your application. Since all applications vary relative to required performance parameters, any suggested substitutes must be tested and qualified in the application.

Should you have any questions or concerns please contact your local Representative, Distributor, or Area Sales Manager.

BMP-12/1.65-D24-C	BWR-5/900-D12A-C	UST-15/200-D5-C
BMP-12/1.65-D48-C	TMP-5/5-15/1-D48	UST-5/500-D5-C
BMP-12/1.65-Q12-C	TWR-30777-C	UWR-12/1250-D5A-C
BMP-12/1.65-Q48-C	TWR-31064-C	UWR-12/1650-D12A
BMP-15/1.3-D24	TWR-5/1000-12/125-D5A-C	UWR-12/1650-D48A-C
BMP-15/1.3-D24-C	TWR-5/1000-12/210-D12A-C	UWR-12/250-D5-C
BMP-15/1.3-D48	TWR-5/1000-12/210-D24A	UWR-12/420-D24-C
BMP-15/1.3-D48-C	TWR-5/1000-12/210-D24A-C	UWR-12/420-D48-C



		Muraia P
BMP-15/1.3-Q12-C	TWR-5/1000-12/210-D48A-C	UWR-12/750-D48A-C
BMP-15/1.3-Q48-C	TWR-5/1000-15/200-D12A-C	UWR-15/1000-D5A-C
BMP-5/4-D24-C	TWR-5/1000-15/200-D24A	UWR-15/1300-D12A-C
BMP-5/4-D48-C	TWR-5/1000-15/200-D48A-C	UWR-15/335-D24
BMP-5/4-Q12-C	TWR-5/1000-15/250-D48A	UWR-15/335-D24-C
BMP-5/4-Q48-C	TWR-5/1200-12/250-D48A-C	UWR-15/335-D48
BMP-5/5-3.3/4-D24-C	TWR-5/1500-12/250-D48A-C	UWR-15/335-D48-C
BMP-5/5-3.3/4-D48-C	TWR-5/1500-15/250-D48A-C	UWR-15/530-D5A-C
BST-12/105-D5-C	TWR-5/1800-15/150-D48A-C	UWR-15/600-D48A
BST-15/85-D5	TWR-5/3000-12/500-D12A	UWR-15/600-D48A-C
BST-15/85-D5-C	TWR-5/3000-12/500-D48A-C	UWR-15/665-D12A-C
BWR-12/105-D5-C	TWR-5/3000-15/500-D12A	UWR-3.3/4250-D5A-C
BWR-12/210-D24-C	TWR-5/3000-15/500-D48A-C	UWR-3.3/4850-D12A
BWR-12/210-D48-C	TWR-5/800-15/150-D5A-C	UWR-3.3/4850-D12A-C
BWR-12/335-D5A-C	UMP-12/2.1-Q12-C	UWR-3.3/4850-D48A-C
BWR-12/625-D5A	UMP-12/2.5-Q48-C	UWR-30521
BWR-12/625-D5A-C	UMP-12/3.3-D48-C	UWR-31046-C
BWR-12/830-D48A-C	UMP-12/3-D24	UWR-5.2/3000-D5A-C
BWR-15/165-D24-C	UMP-12/3-D24-C	UWR-5/1000-D24
BWR-15/165-D48-C	UMP-15/1.7-Q12-C	UWR-5/1000-D24-C
BWR-15/275-D5A	UMP-15/2.5-D24-C	UWR-5/1000-D48-C
BWR-15/275-D5A-C	UMP-15/2.65-D48-C	UWR-5/1000-D48L1-C
BWR-15/500-D5A-C	UMP-15/2-Q48-C	UWR-5/1800-D48A
BWR-15/670-D48A-C	UMP-30514-C	UWR-5/2000-D12A



BWR-15/85-D5-C	UMP-5/5-Q12	UWR-5/2000-D48E-C
BWR-5/1500-D5A-C	UMP-5/5-Q12-C	UWR-5/3000-D5A-C
BWR-5/1700-D12A-C	UMP-5/6-Q48-C	UWR-5/4000-D12A
BWR-5/1700-D48A-C	UMP-5/7-D24-C	UWR-5/4000-D48E-C
BWR-5/500-D48-C	UMP-5/8-D48-C	UWR-5/500-D5-C
BWR-5/700-D5A-C	UST-12/250-D5-C	