THALES

| ID No. 907 | Product Support Notification | Date 07.07.2022 |
|----------------------|------------------------------|---------------------------|
| Product | Ordering Code | |
| See Appendix, Page 2 | | |
| | | |

Reduced Support Offering: Following support and service will be discontinued:

HARDWARE

- \boxtimes Design-in support
- Second source qualification

SERVICES

- Quality assurance (RMA analysis)
- Failure analysis on component level
- Approval recertification (MNO, GCF/PTCRB, ...)

SOFTWARE

Software development (new features)

Limited software maintenance (bug fix)

DOCUMENTATION

Release of technical documents (except security issues)

| Details on Notification: | Thales informs support for products listed in appendix will be limited: | |
|--------------------------|---|--|
| | No new features planned | |
| | No regular renewal of approvals planned, will be evaluated on a case by case basis | |
| | Failure analysis on component level will be limited case by case according to the capabilities of chipset supplier | |
| | For new designs Thales recommends PLS63, PLS83, EXS62, EXS82, ELS62 | |
| | If there are further questions, please contact your local FAE team. | |
| Timing note: | The reduced support offering will be effective 6 weeks after issue date of this notification. | |

| Quality assurance measurements: | No change in existing Quality Management process and philosophy. |
|---------------------------------|--|
|---------------------------------|--|

Attachments: Appendix page 2

7/11/2022

11.07.2022

Southant Х

Program Manager Signed by: SUN Xiao-Lin



Head of Quality Management IoT Signed by: SCHULTZ Clemens

THALES

APPENDIX

| Ordering Code | Product |
|-----------------|--|
| L30960N4400A200 | ELS61-US Rel.2 |
| L30960N4400B101 | ELS61-US Rel.1 MR (customer specific) |
| L30960N4400B110 | ELS61-US Rel.1 (customer specific) |
| L30960N4400B200 | ELS61-US Rel.2 (customer specific) |
| L30960N4400C200 | ELS61-US Rel.2 (customer specific) |
| L30960N4400D200 | ELS61-US Rel.2 (customer specific) |
| L30960N4400E101 | ELS61-US Rel.1 MR (customer specific) |
| L30960N4405A200 | ELS61-US Rel.2 CI |
| L30960N4420A200 | ELS61-USA Rel.2 |
| L30960N4425A200 | ELS61-USA Rel.2 CI |
| L30960N4450A200 | ELS61-E Rel.2 |
| L30960N4450C200 | ELS61-E Rel.2 (customer specific) |
| L30960N4450V101 | ELS61-E Rel.1 MR (customer specific) |
| L30960N4450V200 | ELS61-E Rel.2 (customer specific) |
| L30960N4455A101 | ELS61-E2 Rel.1 MR |
| L30960N4455A110 | ELS61-E2 Rel.1 (customer specific) |
| L30960N4455B101 | ELS61-E2 Rel.1 MR (customer specific) |
| L30960N4460B100 | ELS61-AUS Rel.1 (customer specific) |
| L30960N4460B101 | ELS61-AUS Rel.1 MR (customer specific) |
| L30960N4460C102 | ELS61-AUS Rel.1 (customer specific) |
| L30960N4460I101 | ELS61-AUS Rel.1 MR (customer specific) |
| L30960N4460N101 | ELS61-AUS Rel.1 MR NT |
| L30960N5400I101 | ELS81-US Rel.1 (customer specific) |
| L30960N5405I101 | ELS81-US Rel.1 CI (customer specific) |
| L30960N5450I101 | ELS81-E Rel.1 (customer specific) |