



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000973

DATE: 18-Oct-2019

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	5962-9204201M2A	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	5962-9312501MEA	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DG201ABK	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DG442DJ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1077LZ-66+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1077U-125+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1077U-133+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1085LZ-5B2+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1086LU-12F+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1086LU-12F+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1086LU-440+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1086LU-440+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1086LU-8CL+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1086LU-8CL+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1086Z-42M+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1087LU-13C+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1087LU-13C+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1087LU-210+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1087LU-210+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1087LU-2CL+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1087LU-2CL+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1087LU-66+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1088LU-16+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1088LU-16+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1089LU-266+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1099U-WZ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	DS1099U-WZ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1100LU-150+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1100LU-60+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1100U-150+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1100U-35+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1100U-45+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1100Z-300+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1110LE-300+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1135LU-25+T&R	DS1135LZ-25+T&R	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1135U-30+T&R	DS1135Z-30+T&R	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1135U-6+T&R	DS1135Z-6+T&R	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1250WP-150+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1250YP-100+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1265AB-70+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1312E+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1315EN-5+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1330ABP-70IND+	N/A	18-Oct-2019	18-Oct-2019	The part was not released
Discontinuance	DS1330YP-70IND+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1343D-18+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1343D-18+T&R	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1344E-18+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1344E-18+T&R	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1350ABP-100+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1350ABP-70+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1350WP-150+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1350YP-70+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1350YP-70IND+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1393U-3+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1672-2+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1672U-2+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1685Q-3+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1685Q-3+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1706PEUA+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1708TEPA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS17485SN-5+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1775R6+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	DS1806S-050+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1817-10+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1817-20+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1819BR-5-U+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1822-PAR+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1830A+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1831A+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1831D+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1831E+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1834D+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS1855B-010+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS2401AZ-001-272+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS2401P-115-A4B+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS2411R-042-00+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS2432P-W0F+1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS2432X-S+	DS28E22Q+T	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS2433AX+U	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS2704RQC1A+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS2704RQC1A+T10	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS2781E-A2+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS2781E-A2+T&R	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS28E01G-033-1A+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS28E01G-100+T&R	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS28E01G-100+U	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-5A5-A5+1T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-5A5-A5+2T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS28E15P-W35+1	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS28E15P-W35+1T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS3992Z-18N+T&R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS3992Z-18P+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS3992Z-18P+T&R	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	DS9106L-0G0+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	ICL7107EQH+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	ICL7107EQH+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	ICL7109CMH+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	ICL7109CMH+D	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	ICL7109CMH+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	ICL7109CMH+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	ICL7117CMH+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	ICL7117CMH+D	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	ICL7117CMH+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	ICL7117CMH+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	ICL7621ACSA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	ICL7665ESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	ICM7225IPL+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	ICM7242IWE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	IH5141CPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	LM4040BIM3-2.1+C6K	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	LM4040BIM3-2.5+C5P	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	LM4040BIM3-2.5+C6K	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	LM4040BIM3-5.0+C5P	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	LM4041AEX3-1.2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	LM4041AEX3-1.2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	LM4041CEM3-1.2+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	LM4041CEM3-1.2+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1002CAX+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1002CAX+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1011CEG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1036EKA+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1036EKA+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1037EKA+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1062CEUB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX107ECS+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX107ECS+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1080ACUP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1080AEUP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1080BEUP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1083BEUE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1083BEUE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1084ACSA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1084ACSA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1085AESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX1091AEEI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1092AEEG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1092AEEG+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1092BEEG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1093BCEG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1093BEEG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11041ETC+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11055ECB+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11055ECB+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11058ECB+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11058ECB+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1107EUB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11106ATB+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11106ATB+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11111EEE+TG068	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11124ATI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11124ATI+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11130ATI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11130ATI+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1115EKA+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11162ETB+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11162ETB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX111ACWE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX111AEWE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX111BEPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11215EUG+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1122BEGK+D	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11321ATJ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11321ATJ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11327ATJ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11327ATJ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11329ATJ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11329ATJ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11330ATJ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11330ATJ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1133BEAP+G077	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX1134BEAP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1143ACAP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1144BEAP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1145BEAP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1147BEUP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1154AEUE+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1154AEUE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1159AEUI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX115EAX+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1165AEUI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1165BEUI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1166ACUP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1174BCUP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1175AEUI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1178BCUP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1178BCUP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1179ACUI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1179ACUI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1179BEUI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1187CEUI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1187CEUI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1188CCUP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1188CCUP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1189BEUI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11903ETP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11903ETP+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11905GTP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX11905GTP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1197ECM+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1197ECM+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1205EMH+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1205EMH+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1206ETL+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX120EAG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1213EGK+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1213NEGK+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX1214EGK+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX121EAP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX121EAP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX121MJE	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX122AEWG+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX122AEWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX122BEAG+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX122BEAG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1243AESA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1243AESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1245ACAP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1245AEAP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1245AEAP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1248ACPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1249ACEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX12528ETK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX12528ETK+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX12529ETK+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1254AEUE+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1254AEUE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX12558ETK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX12558ETK+D	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX12558ETK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX12558ETK+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX12559ETK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX12559ETK+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1261BCEI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1261BCEI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1262AEEI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1263BEEG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1265ACEI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1266BCEI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1266BCEI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1267BEEG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1268ACEG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1274AETC+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX1274AETC+T	MAX1237EUA+	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1274BETC+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1274BETC+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1275ACTC+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1277AETC+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1277AETC+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1284ACSA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1288EKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX128ACAI+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX128ACAI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX128AEAI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1291ACEI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1293AEEG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1294ACEI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1294BEEI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1296ACEG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1297AEEG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX13013EXT+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1303AEUP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1306ECM+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX13081EEPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX13182EESD+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX13183EELB+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX13183EELB+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1321ECM+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1321ECM+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX13235EETP+GH7	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX133EQH+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX133EQH+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX13481EETE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX13482EETE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX134EQH+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1365ECM+	N/A	18-Oct-2019	18-Oct-2019	The part was not released
Discontinuance	MAX1365ECM+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1366ECM+	N/A	18-Oct-2019	18-Oct-2019	The part was not released
Discontinuance	MAX1366ECM+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX1368ECM+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX136CPL+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX139CMH+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX139CMH+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX139CMH+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1409CAP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1436ECQ+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1436ECQ+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14577EETX+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14641ETA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14641ETA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1464CAI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14655EWC+CJD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14655EWC+TCJD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14676BEWO+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14676BEWO+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14688EWC+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14688EWC+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX146BEPP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14730EWL+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14730EWL+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14778EETP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX147AEPP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX147CCAP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX147CCAP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14800CCM+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14801CCM+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14805CCM+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14830ETM+G3U	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14830ETM+TG3U	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14885EETL+GH7	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1492CAI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14934AAWE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14934AAWE+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14935AAWE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14935AAWE+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX14979EETX+GH7	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX14982ETO+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX149AEPP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15010ATJ+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15030ATB/V+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15030ATB/V+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15037ATE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15037ATE+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15068ATP+G2Z	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15096AEWE+	MAX15096AGWE+	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15096AEWE+T	MAX15096AGWE+T	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15096EWE+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15096EWE+T	MAX15096GWE+T	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX150ACPP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX150ACWP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX150AEWP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1510ETB+CKG	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1510ETB+TCKG	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1523EUT+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX152CAP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1544ETL+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1544ETL+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX154AEWG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX154AEWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX154BCAG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX154BCAG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15511TGTL+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15511TGTL+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1554ETA+G069	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1554ETA+G40	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1554ETA+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1554ETA+GA4	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15561GTL+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15561GTL+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1556ETB+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1556ETB+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX1556ETB+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1556ETB+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1556ETB+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15576GTG+G2Z	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX15576GTG+TG2Z	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1557ETB+G069	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1561ETA+G069	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX156ACNG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1572ETC130+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1572ETC250+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1573ETE+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1574ETB+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1574ETB+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1577YETA+G47	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1578ETG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1578ETG+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX158BEPI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16003DTE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16004DTP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16005DTE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16006CTG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16007ATP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16007ATP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16007BTP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16016PTBT+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16016PTBT+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16021LTEL+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16021PTEM+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16021PTER+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16021PTEY+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16021PTEZ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16021PTEZ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16024LTBL+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16049ETN+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16055IAUB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1605ETT+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX1605ETT+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16067ETJ+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16068ETI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1607ESA+C71055	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR15T+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR15T+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR20T+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR20T+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16083AXR+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR27H+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR27H+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16084XS41V+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16084XS41V+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16092UK29HOA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16093UK19HOB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16094UK16F+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16095UK22HOB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16096UK44L+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1615EUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1615EUK+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1615EUK+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1615EUK+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1616EUK+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX161BEPI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX161BEWI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX161BEWI+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1627ESA+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX162BCNG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX163BCWG+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX163BCWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX163CEWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX164CCWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX165ACWN+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX165ACWN+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX165AEWN+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX166ACWP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX166ACWP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX166BEWP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX166DCWP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX166DCWP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX166DEWP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX166DEWP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX167BCWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX167CCWG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX167CCWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16828ATT+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16828ATT+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1682EUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1683EUK+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1683EUK+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1683EUK+G40	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1683EUK+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16840ATB+QR	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16840ATB+TQR	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16963RATEC/V+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16963RATEC/V+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16964RAUEA/V+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16964SATEA/V+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16964SAUEA/V+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16965RATEA/V+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16965RAUEA/V+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16965SAUEA/V+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16993ATJL/VY+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16993ATJL/VY+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16999AUA05+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16999AUA05+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16999AUA10+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX16999AUA10+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17036GTL+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17036GTL+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17058X005+T10	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17061AETI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX17061AETI+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17112ETB+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17140AETL+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17140AETL+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1719EUT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1720EUT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1724EZK33+G096	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1724EZK33+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1725EUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1725EUK+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1725EUK+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1726EUK18+G035	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1726EUK18+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1726EUK50+G48	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX172ACWG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX172ACWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1733EUK+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1734EUK18+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1734EUK18+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17409GTI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17410GTM+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17410GTM+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX174ACWI+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX174ACWI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX174BCWI+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX174BCWI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX174CCWI+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX174CCWI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX177CNG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX177CWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17823BGCB/V+GB	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17823BGCB/V+TGB	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17823GCB+	N/A	18-Oct-2019	18-Oct-2019	The part was not released
Discontinuance	MAX17823GCB+T	N/A	18-Oct-2019	18-Oct-2019	The part was not released
Discontinuance	MAX17878GCB/V+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX17878GCB/V+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX178ACWG+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX178ACWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX178BCWG+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX178BCWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX180BEQH+D	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX180BEQH+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX180BEQH+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX180CEQH+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1819EBL25+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1819EBL25+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX181AEQH+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX181AEQH+D	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX181AEQH+TD	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX181BCPL+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX181CEQH+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX181CEQH+D	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX181CEQH+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX182BCWI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1838EEE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1838EEE+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1839EEP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX183ACNG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX185BCNG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX188DEPP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX190ACNG+G002	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX190ACWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1920EUT+G47	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1921EUT18+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1922ETB+C3B	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1928EUB18+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1928EUB25+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1935ETA+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1935ETA+GA4	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1935ETA+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1935ETA15+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1935ETA15+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX19713ETN+GH7	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1976AEZT110+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1976AEZT110+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX1976AEZT285+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX19994AETX+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX19994AETX+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX199BEWI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX199BEWI+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20002CATPC/V+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20002CATPC/V+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20002CATPD/V+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20002CATPD/V+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024AGXXC/V+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024AGXXC/V+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024AGXXD/V+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024AGXXD/V+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024AGXXF/V+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024AGXXF/V+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024BGXXB/V+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024BGXXB/V+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024CGXX/V+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024CGXX/V+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024CGXXC/V+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024CGXXC/V+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024CGXXD/V+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024CGXXD/V+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024DGXXK/V+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024DGXXK/V+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024EGXX/V+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20024EGXX/V+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20070GTJA/V+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX20070GTJA/V+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX2010ETI+GH7	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX2042ETP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX2045ETJ+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX2047ETJ+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX2062ETM+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX207EAG+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX208EWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX2136AETJ/V+Q00	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX2136AETJ/V+TQ00	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX24106EXV+T	MAX24107EXV+T	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX250CSD+G55	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX2552ETN+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX260BEWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX261ACNG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX261ACWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX261AENG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX261AEWG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX261AEWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX262ACWG+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX262ACWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX263AEWI+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX264AEWI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX2659ELT+CGA	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX2659ELT+TCGA	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX267BEWG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX267BEWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX2901ETI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX293MJA	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX296EPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3032ECUE+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3042BCWE+G126	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3044EWE+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3056ASD+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3086ECPD+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3086EPD+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX308EJE	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3096CSE+C23	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX31182AUA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX31182AUA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX31182AUA/V+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX31182AUA/V+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3207EAUT+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3212EAI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3224EAP+G2X	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3224ETP+G2X	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3224EUP+G2X	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3225EAP+G2X	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3225EUP+G2X	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3226EAE+G2X	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3227EAE+G2X	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3244EAI+G2X	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3265EUE+D	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3265EUE+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3272AETP+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3273ETG+D	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3273ETG+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3280EAUK+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3293AUT+G069	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3294AUT+CGD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3294AUT+TCGD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3317ECAP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX336CUI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX336CUI+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3370ELT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3370EXK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3371EXT+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3373EEKA+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3373EEKA+G0N	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3373EEKA+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3373EEKA+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3373EEKA+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3376EEKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3376EEKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3378EETD+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3378EETD+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3430MSA/PR3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX3440EAPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3443ESA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3460CSD+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3518ETP+CHK	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3518ETP+TCHK	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX3799E/D	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX396EQI+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX396EQI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX399CEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4031EESD+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4031EESD+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4038AAUA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4043ESD+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4043ESD+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX406BC/D+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4070ATA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4070ATA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4077ESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4091AUA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4091AUA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4091AUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX409AESA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX409AESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4122EUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4165EUK+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX417EPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4193CSA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4193CSA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4202ESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4205EUA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4210DETT+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4210DETT+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4212EUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4223EUT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4230AXK+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4232AKA+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX4232AKA+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4232AKA+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4233ABC+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4236EUT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4236EUT+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4236EUT+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4237BEUA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4237BEUA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4245AXT+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4250EUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4250EUK+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4253EBC+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4253EBC+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4253ESD+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4256EUA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4256EUA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4266ESA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4266ESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4271ESA+TG068	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4281ESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4304EUK+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4322EUK+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4322EUK+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4322EUK+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4330EUK+G075	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4350EXK+G075	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4377TAUA+G65	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4377TAUA+TG65	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4386EEUD+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4386EEUD+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4400AXK+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4400AXK+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4401AXT+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4401AXT+G126	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4401AXT+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4401AXT+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX4412EXK+TG21	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4415ESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX44260AYT+CGU	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX44260AYT+T10CGU	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX44260AYT+TCGU	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX44264EWT+CLA	N/A	18-Oct-2019	18-Oct-2019	The part was not released
Discontinuance	MAX44264EWT+TCLA	N/A	18-Oct-2019	18-Oct-2019	The part was not released
Discontinuance	MAX4430EUK+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4430EUK+TG077	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4431EUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4431EUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4435EUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4435EUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4451EKA+G069	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4461UESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4470EWT+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4470EWT+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4482AUA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4487ASD+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4487ASD+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4490AUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4490AXK+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4490AXK+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4491AKA+G29	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4493AXK+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4501CSA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4501CSA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4502EXK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4504CSA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4515CSA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4542CSA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4560CSE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4580CPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4582ASE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4591CUE+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4592CSE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX4592EUE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4609CPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4615CSD+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4631EPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4636ETB+TG104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4695EGC+WGT069	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4754EBE+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4754EBE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4754ETE+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4754ETE+WG104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4795EUK+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4795EUK+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4802CQI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4806CTN+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX481MJA	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX489ECSD+G126	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4906ELB+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX4906FELB+G069	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5023SASA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5026EUT+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5026EUT+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX503ENG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX503EWG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX503EWG+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5071CASA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX507BENG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX508AEWP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX508AEWP+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5093AATE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5096AATE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5096AATE+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX509ACPP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5105EEP+TG035	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5110GWX+G074	MAX5113GWX+TG074	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5111GWX+G074	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5112GWX+TG074	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX5130AEEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5131AEEE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5131AEEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5150BEEE+C40249	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5152AEEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5153ACEE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5153ACEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5154BEPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5157BCEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5158EPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5159CEE+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5159CEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5161LEZT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5161LEZT+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5161LEZT+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX516AENG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5172BEEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5175AEEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5176AEEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5188BEEI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5188BEEI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5191BEEI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5191BEEI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX519BESE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX519BESE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5202ACUB+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5202ACUB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5204ACUB+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5204ACUB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5205AEUB+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5205AEUB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5207ACUB+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5207ACUB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX520AEPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX520BCAP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5222EKA+G0N	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX5234AEUB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5234BEUB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX525BCAP+G068	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX528EPP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5295EUE+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5295EUE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX530BEAG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX531AEPD+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX533BCPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5361PEUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5361PEUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX537ACPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5381MEUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5385EUT+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5393NAUD+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5393NAUD+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5395LATA+G2Z	MAX5395LATA+T	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5395LATA+TG2Z	MAX5395LATA+T	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5418META+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5423ETA+G035	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5428ETA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5428ETA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5429ETA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5429ETA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX543BEJA	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX543BEWE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5443BEUA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5443BEUA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX544AESA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX544AESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX544BEP A+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5452EUB+TG071	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5456ETE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5457ETE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX545AEPD+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX545AESD+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX545BCPD+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5492LA07538+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5492LA07538+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5492LA10000+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5492LA10000+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5492LB07538+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5492LB07538+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5492LC07538+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5492LC07538+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5581AEUP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5581BEUP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5583EUP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5585EUP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5621UCB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5632UCB+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5632UCB+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5733BETN+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5734AUTN+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5734BETN+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5735BETN+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX58000EXW+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5853ETL+GH7	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5859AEXW+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5860HUXH+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5860PUXH+CKD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5881CXW+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5905ESA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5909UEE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX5909UEE+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6002EUR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6029EUK30+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6029EUK50+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6034AEXR30+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6034BEXR30+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6037BAUK21+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6037BAUK21+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6037BAUK30+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6037BAUK30+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6037CAUK41+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6037CAUK41+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6041AEUR+G55	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6041BEUR+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6041BEUR+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6066AEUR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6066AEUR+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6068BEUR+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6068BEUR+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6101EUR+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6105EUR+G075	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6125EUR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6133BASA30+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6133BASA30+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6138BEXR21+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6138BEXR21+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6138CEXR33+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6138CEXR33+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6138CEXR41+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6138CEXR41+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6143BASA41+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6143BASA41+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6150ESA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6150ESA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6194CESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6225AEPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX629ESA+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6306EUK25D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6306EUK44D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6306EUK44D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6306UK25D1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6306UK25D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6306UK28D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6306UK28D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6306UK43D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6306UK43D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6309UK27D1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6309UK27D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6309UK27D2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6309UK32D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6309UK42D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6309UK44D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6309UK46D4+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6312EUK29D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6312UK43D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6312UK44D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6312UK44D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6312UK46D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6312UK46D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6312UK46D4+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6312UK46D4+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US25D4+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US25D4+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US28D4+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US28D4+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US28D4+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US30D4+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US30D4+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US31D4+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US40D4+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US40D4+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US41D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US41D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US42D2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US42D2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US46D1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US46D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US46D3+GA5	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US47D2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US47D2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6314US48D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6314US48D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US26D1+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US26D2+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US26D2+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US26D3+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US26D3+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US26D3+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US26D3+G48	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US26D3+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US26D4+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US29D2+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US29D3+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US29D3+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US29D3+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US29D3+GA4	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US29D3+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US30D1+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US31D3+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US45D1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US45D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US45D3+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US46D3+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6315US46D3+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6316LUK25AY+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6316LUK25AY+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6316LUK26DZ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6316LUK26DZ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6316LUK46CZ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6316LUK46CZ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6316MUK31CY+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6316MUK31CY+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6316MUK47BY+C0K	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6318LHUK27CY+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6318LHUK27CY+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6318MHUK29CY+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6318MHUK46CY+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6318MHUK46CY+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6319LHUK26A+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6319LHUK26C+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6319MHUK46C+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6320PUK29CZ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6320PUK29CZ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6320PUK42CW+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6320PUK42CW+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6321HPUK26CY+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6323DUT46+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6323DUT46+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6324BUT23+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6324BUT23+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6326UR22+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6326UR24+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6326UR24+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6327UR24+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6327UR24+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6327UR25+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6327UR25+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6327UR27+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6327UR27+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6327UR28+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6327UR30+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6327UR30+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6327XR22+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6327XR30+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6327XR30+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6328UR22+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6328UR23+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6328UR24+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6328UR24+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6328UR25+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6328UR28+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6328UR29+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6328UR31+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6328XR25+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6328XR25+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6328XR27+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6328XR27+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6331TUR+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6332UR18D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6332UR22D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6332UR24D1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6332UR24D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6333UR17D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6333UR17D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6333UR19D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6333UR19D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6333UR23D2+C07	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6333UR24D1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6333UR24D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6333UR24D2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6333UR24D2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6333UR25D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6333UR25D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6334UR23D3+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6334UR23D3+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6334UR24D1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6334UR24D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6335US22D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6336US23D3+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6336US25D3+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6336US25D3+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6337US16D2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6337US16D2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6337US22D2+G40	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6337US24D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6337US24D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6339KUT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6340UK40+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6340UK40+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6342RUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6343LUT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6343SUT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6343SUT+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6344ZUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6344ZUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6345SUT+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6345SUT+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR34+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR34+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR35+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR35+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR36+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR36+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR37+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR37+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR38+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR38+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR39+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR39+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR40+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR40+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR41+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR41+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR42+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR42+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR43+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR43+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR45+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346UR45+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346XR33+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346XR33+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346XR35+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346XR35+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6346XR37+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6348UR36+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348UR36+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348UR37+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348UR37+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348UR38+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348UR38+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348UR39+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348UR39+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348UR41+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348UR42+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348UR42+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348UR45+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348XR40+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348XR40+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348XR41+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348XR41+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348XR43+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6348XR43+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6349TPUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6349TPUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6349YHUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6349ZPUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6349ZPUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6351LRUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6351SYUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6351SYUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6352MSUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6352MSUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6352RVUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6352SWUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6352SWUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6352TYUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6352TYUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6352TZUK+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6353LRUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6353LRUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6353LTUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6353LTUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6353SVUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6353SVUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6353UVUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6353UVUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6353UWUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6354RVUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6354RVUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6354SVUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6354SVUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6354SWUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6354SWUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6354TZUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6354TZUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6354UWUK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6354UWUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6355MTUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6355MTUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6355SYUT+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6355TVUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6355TVUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6355TYUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6355TYUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6356RVUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6356RVUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6356TWUT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6356UVUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6356UVUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6357LSUT+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6357SWUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6357SWUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6357SYUT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6357TYUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6357TYUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6357UWUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6357UWUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6358SZUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6358SZUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6358TYUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6358TYUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6359TZUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6359TZUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6360RVUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6360RVUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6360SWUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6360SWUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6361HUT44+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6361HUT44+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6361HUT46+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6361HUT46+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6361LUT29+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6361PUT29+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6361PUT29+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6362HUT23+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6362HUT23+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6362HUT26+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6362HUT26+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6362HUT29+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6362HUT29+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6362HUT31+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6362HUT31+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6362HUT46+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6362HUT46+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6364PUT44+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6364PUT44+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6365PKA31+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6366PKA29+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6366PKA46+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6367HKA29+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6367HKA29+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6367PKA29+G035	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6367PKA31+G035	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6367PKA44+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6368LKA26+G0N	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6369KA+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6369KA+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6370KA+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6373KA+G48	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6373KA+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6375UR25+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6375UR25+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6375XR25+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6375XR25+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6377UR24+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6377UR24+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6377UR30+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6377UR30+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6377XR30+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6377XR30+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380UR33+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380UR33+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380UR34+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380UR34+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380UR41+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380UR41+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380UR42+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380UR42+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380UR43+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380UR43+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380UR44+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380UR44+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380XR42+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380XR42+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6380XR43+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6381XR16D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6381XR16D2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6381XR16D2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6386XS40D1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6386XS40D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6386XS45D1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6386XS45D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6386XS45D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6386XS45D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6386XS46D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6387XS16D3+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6387XS17D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6387XS17D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6387XS23D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6387XS23D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6387XS25D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6387XS25D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6387XS44D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6387XS44D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS17D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS17D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS20D1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS20D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS20D2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS20D2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS20D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS20D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS23D2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS23D2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS26D2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS26D2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS26D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS31D3+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS31D3+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS46D1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS46D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS46D2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6389XS46D2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6390XS22D4+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6390XS22D4+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6390XS23D4+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6391KA26+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6391KA26+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6392KA17+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6392KA29+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6392KA29+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6392KA29+TG071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6392KA31+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6392KA31+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6397LATA+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6397MATA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6399ATA+GA4	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS23+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS23+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS24+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS24+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS25+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS25+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS26+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS26+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS27+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS27+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS28+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS28+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS31+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6400BS31+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6402BS23+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6402BS23+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6402BS24+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6402BS24+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6402BS25+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6402BS25+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6402BS26+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6402BS26+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6402BS27+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6419UK16+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6419UK17+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6419UK17+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6419UK21+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6419UK21+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6419UK22+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6419UK23+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6419UK23+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6419UK26+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6419UK50+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6419UK50+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6420UK17+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6420UK17+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6420UK23+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6420UK23+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6420UK29+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6420UK44+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6420UK44+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6420UK50+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6420UK50+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421US16+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421US16+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421US17+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421US17+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421US22+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421US22+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421US23+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421US23+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421US31+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421US31+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421US44+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421US44+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421XS17+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421XS17+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421XS23+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6421XS23+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6425UK39+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6425UK40+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6425UK40+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6425UK44+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6425UK44+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6426UK39+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6427EIUR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6427KQUR+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6427KQUR+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6428AGUR+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6428AGUR+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6428DHUR+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6428EHUR+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6428EIUR+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6435UK+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6435UK+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTDHRD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTDHRD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTDHSD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTDHSD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTEHRD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTEHRD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTEHSD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTEHSD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTEIRD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTEIRD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTEISD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTEISD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTFJTD7+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTFJTD7+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTKQSD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6440UTKQSD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6441KADHRD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6441KADHRD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6441KADHSD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6441KADHSD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6441KAEHRD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6441KAEHRD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6441KAEHSD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6441KAEHSD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6441KAEIRD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6441KAEIRD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6441KAEISD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6441KAEISD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6441KAKQVD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6441KAKQVD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6443US46L+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6443US46L+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6446UK23L+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6446UK23L+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6446UK26L+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6446UK26L+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6447UK16L+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6447UK16L+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6447UK23L+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6447UK23L+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6447UK29L+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6453UT23S+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6453UT23S+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6453UT29S+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6453UT31S+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6453UT31S+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6454UT16S+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6454UT23S+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6454UT26S+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6454UT26S+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6454UT31S+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6454UT31S+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6454UT46S+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6454UT46S+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6456UT26S+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6456UT26S+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6457UKD0A+G075	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6457UKD0A+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6459UTB+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461UK16+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461UK16+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461UK22+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461UK22+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461UK29+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461UK29+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461UR40+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461UR40+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461UR46+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461UR46+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461XR18+GA7	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461XR40+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461XR40+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461XR44+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6461XR44+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UK29+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UK29+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UK31+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UK31+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UK53+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UK53+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UR16+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UR16+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UR17+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UR17+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UR23+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UR23+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UR26+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UR26+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UR29+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UR29+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UR35+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6463UR53+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6466XR24+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6466XR24+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6466XR25+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6466XR25+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6466XR34+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6466XR34+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6466XR42+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6466XR42+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467US16D7+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467US16D7+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467US29D7+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467US29D7+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467US30D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467US30D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467US31D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467US31D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467US42D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467US42D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467XS23D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467XS23D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467XS27D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467XS27D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6467XS29D3+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6468US30D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6468US30D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6468US31D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6468US31D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6468XS23D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6468XS23D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6468XS46D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6468XS46D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6469TA33AD3+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6469TA33AD3+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6471TA30AD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6474TA15AD3+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6474TA15AD3+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6495ATT+G128	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX649ESA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX649ESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6501UKP090+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6501UKP095+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6501UKP105+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6501UKP105+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6501UKP115+G48	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6505UTP060+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6505UTP060+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6505UTP115+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6508UT0A32+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6508UT0A32+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6509HAUK+G075	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6509HAUK+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6510CAUT+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6510HAUT+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6512UT085+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6512UT095+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6512UT105+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6512UT105+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6513TT125+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6513TT125+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6517UKP055+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6517UKP055+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6519UKP085+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6519UKP085+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6519UKP105+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX651ESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6610AUT+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6613MXK+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6613MXK+G47	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX66242E/D+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX66242E/D+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX66242E/D+U	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX66242E/D+UW	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX66242E/W+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX662AMSA/PR+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX662AMSA/PR+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX66300AETN+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX66300AETN+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6642ATT90+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6642ATT90+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6642ATT90+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX667MSA/PR+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX667MSA/PR+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6685AU40H+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6686AU40H+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6697UP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6698EE34+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6698EE9C+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6698EE9C+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6698UE9C+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6698UE9C+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6701AMKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6701AMKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6701ARKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6701ARKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6701AYKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6701AYKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6701LKA+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6701RKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6701YKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6703ALKA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6703ALKA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6703ASKA+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6703SKA+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6703SKA+G48	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6703TKA+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6704TKA+G0N	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6705ASKA+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6705MKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6705MKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6705YKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6705ZKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6705ZKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6706MKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6706MKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6706RKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6706TKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6706TKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6706YKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6706YKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6706ZKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6707AMKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6707AMKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6707ATKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6707ATKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6707AYKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6707AYKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6707YKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6707YKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6708SKA+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6708SKA+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6710IUT+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6710IUT+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6710KUT+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6710NUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6710NUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6710QUT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6711LEXS+10	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6711LEXS+T10	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6712REXS+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6712REXS+10	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6712REXS+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6712REXS+T10	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6713LEXS+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6715UTLTD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6719AUTWGD3+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6719AUTWGD3+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6719UTSDD1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6719UTSDD1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6719UTSYD2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6719UTSYD2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6719UTTGD1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6719UTTGD1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6719UTTZD1+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6719UTTZD3+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6719UTZWD1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6719UTZWD1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6721UTYDD3+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6721UTYDD3+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6722UTYDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6722UTYHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6722UTZGD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6723AUTVDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6723AUTVHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6723UTLTD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6723UTSDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6723UTVDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6723UTVHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6723UTWGD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6723UTYDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6724UTLTD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6724UTRVD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6724UTSVD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6724UTTGD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6724UTVDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6724UTYHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6724UTZWD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6725AKARVD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6725KAYDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6725KAYHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6725KAZGD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6726AKALTD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6726AKASHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6726AKATGD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6726KARVD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6726KAVDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6726KAWGD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6726KAYDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6726KAYHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6726KAZWD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6727KASHD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6727KASHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6727KASVD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6727KASVD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6727KASYD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6727KASYD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6727KATGD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6727KAVDD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6727KAVDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6727KAVHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6727KAWGD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6727KAZGD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6728KATWD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6728KAZGD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6730UTLD3+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6730UTLD3+GA5	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6731AUTTD3+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6731AUTTD3+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6733UTSYD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6734AKAWGD3+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6734AKAWGD3+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6734KASYD3+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6734KAZGD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6734KAZWD3+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6736XKRVD7+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6736XKRVD7+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6736XKZGD3+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6736XKZGD3+TG05	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6737XKLTDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6737XKRVD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6737XKSDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6737XKSYD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6737XKVDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6737XKVHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6740XKRVD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6740XKSHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6740XKSVD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6740XKVHD3+	N/A	18-Oct-2019	18-Oct-2019	The part was not released
Discontinuance	MAX6740XKVHD3+T	N/A	18-Oct-2019	18-Oct-2019	The part was not released
Discontinuance	MAX6740XKVRD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6740XKYDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6740XKYHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6740XKZWD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6743XKSHD3+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6743XKSVD3+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6743XKSVD3+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6743XKVDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6743XKVHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6743XKVRD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6743XKWTD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6743XKYDD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6743XKYHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6743XKZGD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6744XKRVD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6744XKSDD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6744XKSHD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6744XKSHD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6744XKSVD3+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6744XKSVD3+TGA8	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6744XKSYD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6744XKVDD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6744XKZWD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6745XKLD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6746KA29+G48	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6751KA22+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6751KA22+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6752KA29+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6752KA32+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6753KA29+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6753KA44+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6754UKLD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6754UKRD0+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6754UKRD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6754UKRD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6754UKRD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6754UKTD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6754UKWD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6754UKZD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6756UKRD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6756UKRD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6756UKTD0+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6756UKWD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6756UKZD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6757UTLD0+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6757UTLD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6757UTRD0+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6757UTRD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6757UTRD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6757UTRD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6757UTTD0+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6757UTTD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6757UTWD0+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6757UTWD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6757UTZD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6757UTZD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6757UTZD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6762TATZD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6762TAWED3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6791TPLD1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6791TPTD2+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6791TPTD2+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6792TPSD2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6794TPLD2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6794TPLD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6795TPLD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6800UR26D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6800UR26D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6800UR44D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6800UR44D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6800UR46D1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6800UR46D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6801UR44D3+GA5	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6802UR26D1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6802UR26D1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6802UR26D2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6802UR26D2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6802UR46D2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6802UR46D2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6802UR48D3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6802UR48D3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6803US31D3+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6803US31D3+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6804US26D3+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6804US29D3+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6806US26+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6806US26+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6806XR26+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6806XR26+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6807UR26+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6807UR26+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6807UR46+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6807UR46+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6807US26+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6807US26+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6807XR26+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6807XR26+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6807XR46+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6807XR46+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6808US26+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6808US26+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6808US46+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6808US46+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6808XR46+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6808XR46+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6814XK+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6816EUS+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6816EUS+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6816EUS+G48	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6816EUS+G52	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6816EUS+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6816EUS+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6817EUT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6820UT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6820UT+GA4	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6823WUK+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6824VUK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6826RUT+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6826RUT+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6826WUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6826WUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6826YUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6826YUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6828RUT+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6828RUT+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6829TIUT+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6829VDUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6829YDUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6829ZWUT+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6829ZWUT+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6831SDUT+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6831SDUT+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6831SZUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6831VDUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6831VDUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6831YDUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6831YHUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6831ZGUT+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6831ZGUT+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6834IXRD3+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6834WXR0+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6834WXR0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6835HXSD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6835IXSD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6835IXSD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6835WXSD0+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6835WXSD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6835WXSD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6835WXSD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6835WXSD4+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6835WXSD4+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6836HXSD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6836WXSD1+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6836WXSD1+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6837FXSD2+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6837FXSD2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6837GXSD0+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6837GXSD0+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6837GXSD2+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6837HXSD3+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6837HXSD3+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6837HXSD3+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6837VXSD0+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6837VXSD0+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6838XSD0+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6842DUKD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6842DUKD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6842GUKD4+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6842GUKD4+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6842HUKD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6842HUKD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6847KARD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6847KARD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6847KAWD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6847KAWD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6847KAZD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6847KAZD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6848KARD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6848KARD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6848KARD7+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6848KARD7+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6848KASD3+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6848KASD3+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6848KATD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6848KATD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6848KAWD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6848KAWD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6848KAZD3+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6848KAZD3+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6854UK23D2+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6854UK23D2+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK16+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK16+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK18+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK18+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK19+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK19+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK23+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK23+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK24+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK24+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK26+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK26+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK31+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX6861UK31+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK46+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6861UK46+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6864UK20D4S+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6864UK20D4S+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6872ETJ+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6874ETJ+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6875ETJ+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6881ETE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6887BETE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6887OETE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6887RETE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6887RETE+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6888BETE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6888DETE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6888FETE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6888JETE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6888KETE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6888OETE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6890ETI+T	MAX16065ETM+	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6893ETI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX690ACSA+TG002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX690MLP/883B	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX691AC/D	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX693AEUE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6956ATL+GH7	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6961ATH+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6963ATH+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX6964ATG+G40	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7032ATJ+TWC6L	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX703CSA+G068	MAX703CSA+	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7043EUI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7043EUI+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX704SMJA	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX704TCPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX705ESA+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX706SCSA+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX709RPCA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX709REPA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX709SCUA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7300ATI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7301ATL+GH7	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7307AUB+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7311ATG+GH7	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7317ATE+GH7	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7359ETG+G47	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX737EWE+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX737EWE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7411CPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX743EWE+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7502MUA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7502MUA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7503MSA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7645ACWP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7645ACWP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7645BCWP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX7645BCWP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX77100EWL+CGC	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX77100EWL+TCGC	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX77807EWJ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX77807EWJ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX791EUE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX791EUE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX792LESE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX792MEPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX792SEPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX795TCPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX797CSE+G068	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX797EPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX800LCPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX800LCUE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX800LEUE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX800MCSE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX800MCSE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX800MCUE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX800MESE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX800MESE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX801LESA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX801LESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX801NCPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX802RCPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX802RCSA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX802SESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX802TCSA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX802TCSA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX803LEXR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX803LEXR+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX803SEXR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX803SEXR+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX803SEXR+GA4	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX803TEXR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX803TEXR+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX803ZEXR+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX804SCPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX804SCSA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX804TCSA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX805SCPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX805TCPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX807MEUE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX807MEUE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX808LEPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX808MCPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX808MESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX808NCPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809JEUR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809LEUR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809LEUR+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809LEUR+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX809LEUR+GA5	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809LEUR+TG05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809MEUR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809MEUR+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809MEUR+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809MEXR+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809REUR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809REUR+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809REUR+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809REXR+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809SEUR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809SEUR+G035	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809SEUR+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809SEUR+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809SEUR+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809SEUR+G19	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809SEUR+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809SEUR+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809SEUR+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809SEXR+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809TEUR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809TEUR+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809TEUR+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809TEUR+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809TEUR+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX809TEUR+GA4	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX810LEUR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX810LEUR+G55	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX810MEUR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX810REXR+10	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX810REXR+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX810REXR+T10	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX810SEUR+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX810SEUR+G069	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX810SEUR+GA5	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811LEUS+G035	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX811LEUS+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811REUS+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811REUS+GA3	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811SEUS+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811SEUS+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811SEUS+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811SEUS+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811SEUS+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811SEUS+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811SEUS+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811SEUS+GC3	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811SEUS+GC4	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811TEUS+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811TEUS+G035	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811TEUS+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811TEUS+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811TEUS+G126	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX811TEUS+G40	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX812LEUS+G035	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX812SEUS+G035	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX812TEUS+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX814NCPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX815KCPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX817MEPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX818MCPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX818MCUA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX818MCUA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX819LCPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX820SCSE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX820SESE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8213AMJE	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX821LUS+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX821MUS+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX821RUS+G069	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX821SUS+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX821TUS+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX821TUS+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX822SUS+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX823LEUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX823REUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX823SEUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX823SEUK+G035	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX823SEUK+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX823SEUK+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX823SEXK+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX823TEUK+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX823TEUK+G126	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX823TEXK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX824LEUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX824MEXK+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX824REUK+GA5	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX825REXK+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX825SEUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX825TEUK+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX828EUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX829EUK+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX829EUK+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX836EUS+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX837EUS+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX837EUS+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX845ESA+G55	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510ETA25+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510ETA30+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK16+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK16+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK18+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK18+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK21+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK25+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK27+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK28+G47	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK28+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX8510EXK29+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK29+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK29+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK30+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK30+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK33+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK33+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK33+GC7	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8510EXK45+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK15+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK15+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK15+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK18+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK18+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK26+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK26+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK28+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK28+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK28+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK29+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK33+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK33+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK33+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8511EXK35+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8512ETA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8512ETA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8512EXK+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8512EXK+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8512EXK+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8512EXK+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8530EBTJJ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8530EBTJJ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8530ETTG2+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8530ETTG2+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8532EBTJ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8532EBTJ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX8559ETA18+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETA22+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETA88+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAAA+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAAG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAAG+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAAJ+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAAJ+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETADK+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETADK+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETADK+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAG2+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAGG+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAJ1+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAJ1+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAJ1+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAJ2+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAJ2+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAJJ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAJJ+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8559ETAJJ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8560EZK+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8560EZK+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8563EEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8571EUT+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8588ETM+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8588ETM+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8595XETA+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8595XETA+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8595XETA+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8595ZETA+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8595ZETA+G40	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8595ZETA+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8596XETA+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8600AETD+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8600ETD+G069	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX8606ETD+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8607ETD+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8607ETD+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8607ETD+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX860CUA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX860CUA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8614BETD+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8614BETD+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8620YETD+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8620YETD+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8627ETD+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8627ETD+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8627ETD+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8630ZETD18+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8633ETA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8635ETA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8635ETA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT12+G47	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT12+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT13+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT16+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT18+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT19+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8664BEEP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8664BEEP+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX867ESA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX867ESA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8694LEWG+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX870EUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX870EUK+G035	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX871EUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8727ETB+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8727ETB+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8778ETJ+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8778ETJ+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8804WETA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX8804WETA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8805WEWEAE+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8814ETA+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8814ETA+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8814ETA+TWG104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8814ETA+WG104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX882CSA+TG074	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8863SEUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8863SEUK+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8863SEUK+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8863SEUK+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8863TEUK+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8863TEUK+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8863TEUK+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8863TEUK+GA5	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8867EUK33+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8867EUK40+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8868EUK25+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8868EUK50+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8873SEUK+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8873SEUK+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8875EUK33+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8877EUK25+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8877EUK26+GA7	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8877EUK30+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8877EUK32+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8877EUK33+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8877EUK50+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8877EUK50+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8877EZK28+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8877EZK28+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8878EUK33+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8878EZK28+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8878EZK30+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8878EZK30+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8878EZK32+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX8878EZK32+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8878EZK36+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8878EZK36+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8880EUT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8881EUT25+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8881EUT33+G071	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8882EUTA5+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8885EUK27+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8887EZK18+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8887EZK18+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8887EZK25+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8887EZK25+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8887EZK25+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8887EZK27+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8887EZK28+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8887EZK29+GA3	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8887EZK33+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8887EZK33+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8887EZK33+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8888EZK15+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8888EZK29+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8888EZK29+T	N/A	18-Oct-2019	18-Oct-2019	The part was not released
Discontinuance	MAX8901AETA+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8901AETA+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8901BETA+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8901BETA+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8901BETA+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8901BETA+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8973BEWI+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX8983EWE+CAX	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9052BESA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9052BESA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9053BEUB+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9053BEUB+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9111EKA+G035	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9112EKA+G077	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX9173ESE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9173ESE+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9180EXT+G002	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX920EUK+TG071	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9224ETI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX922CPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX924CPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX924EPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9259GTN/V+GG6	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9259GTN/V+TGG6	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9313ECJ+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9317CECJ+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9370EKA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9370EKA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9382ESA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9382EUA+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9382EUA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9491ETP010+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9491ETP080+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9491ETP080+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9502GELT+G104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9502GELT+GA8	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9510AUA+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX954EPA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9693EEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9700AEBC+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9700AEBC+G51	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9700AEBC+GC1	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9710EUE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9710EUE+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9717CETA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9717CETA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9717DETA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9717DETA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9718BETB+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9718BETB+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MAX9718CETB+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9719DEBE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9719DEBE+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9722AETE+G069	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9722BETE+WG104	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9723BETE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX977EEE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX977EEE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX977ESD+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX977ESD+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX98308EWC+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX98308EWC+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX98357BETE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX98357BETE+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX983CSA+G126	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX983CSA+TG126	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX984CPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX984EPE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9850ETI+G47	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9867EWV+G47	N/A	18-Oct-2019	18-Oct-2019	The part was not released
Discontinuance	MAX986ESA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX986ESA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9890AEBL+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9890AEBL+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9890AETA+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9890AETA+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9911EXT+G50	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9915EXT+G05	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9928FABT+G45	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9928FABT+TG45	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9963BGCCQ+WB3R	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9981ETX+D	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9981ETX+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9981ETX+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9982ETP+D	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MAX9982ETP+TD	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MX674AJCWI+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX674AJCWI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX674AJEWI+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX674AJEWI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX674AJP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX674AJP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7225KCWG+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7225KCWG+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7225KP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7248JP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7521JCWN+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7521JCWN+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7523JEWE+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7523JEWE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7523KCWE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7523LCWE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7524KESE+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7524KESE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7528JEW+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7528JEW+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7530LCWE+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7530LCWE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7533JP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7533JP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7533KEWE+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7533KEWE+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7533LP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7533TQ	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7534KCWP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7534KCWP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7535JCWI+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7535JCWI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7535KCWI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7536JCWI+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7536JCWI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7536JP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MX7537KCWG+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7537KCWG+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7537KN+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7537KP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7541AJP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7541KCWN+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7541KCWN+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7542JP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7542JP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7542KP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7542KP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7543JP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7543JP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7545ALP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7545GLCWP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7545KEWP+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7545KEWP+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7545KP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7545LCWP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7545LCWP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7545LP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7547KP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7572JCWG05+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7572JCWG05+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7572KCWG12+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7575KCWN+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7576JP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7578KN+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7581JN+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7582KP+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7582KP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7672KN03+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7821KP+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7828LCWI+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7845KR+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MX7845KR+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Nov-2019

Discontinuance	MXD1810XR41+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1810XR41+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1811UR41+G11	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1812XR46+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1815UR22+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1815UR22+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1815UR23+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1815UR23+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1815UR26+	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1815UR26+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1815UR29+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1815XR22+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1815XR23+T	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1816UR29+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1816UR29+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXD1818UR29+G24	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXL1543BCAI+	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	MXL1543BCAI+T	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	REF02CSA+G107	N/A	18-Oct-2019	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT1157SAFQ	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT1165SFQ	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT1318MFQX	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT1626SFQ	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT1677SBFQ	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT1697SBFQ+CN9	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT1697SBFQ+CNR	N/A	18-Oct-2019	18-Oct-2019	The part was not released
Discontinuance	VT260BWFQ-ADJ	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT262WFQ-ADJ	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT263WFQ-ADJ	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT266WFQ-ADJ	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT267AWFQ-ADJ	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT271SFQ	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT356FCX-ADJ	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT356FCX-ADJ-005	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured
Discontinuance	VT356FCX-ADJ-007	N/A	16-Jan-2020	18-Apr-2021	Part can no longer be manufactured