



## Product Change Notification - SYST-07GCJG163

---

**Date:**

08 Jun 2019

**Product Category:**

Ethernet Switches

**Affected CPNs:**



**Notification subject:**

Data Sheet - VSC7438-02, VSC7464-02, and VSC7468-02 Data Sheet

**Notification text:**

SYST-07GCJG163

Microchip has released a new DeviceDoc for the VSC7438-02, VSC7464-02, and of devices. If you are using one of these read the document located at [VSC7438-02, VSC7464-02, and VSC7468-02 Data Sheet](#).

**Notification Status:** Final

**Description of Change:**

- 1) The Design Considerations chapter was updated with an issue regarding VCAP ES0 actions and SDLB . For more information, see Design Considerations
- 2) The Pin Strapping table has been updated.

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Manufacturability

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 08 Jun 2019

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

**Attachment(s):**

[VSC7438-02, VSC7464-02, and VSC7468-02 Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

**Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

VSC7438YIH-02

VSC7464YIH-02

VSC7468YIH-02