

# Product/Process Change Notice - PCN 18\_0036 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. Any inquiries or requests with this PCN (additional data or samples) must be sent to ADI within 30 days of publication date. ADI contact information is listed below.

PCN Title: ADGM1304 Die Revision, Datasheet Change and Assembly Site transfer for Select

side by side LFCSP in ASE Korea (AEK)

Publication Date: 02-Oct-2019

Effectivity Date: 04-Jan-2020 (the earliest date that a customer could expect to receive changed material)

**Revision Description:** 

Initial Release

## **Description Of Change:**

All layer re-design of the driver IC used in the ADGM1304.

This re-design has widened supply voltage range. There is minor pin out configuration changes of the ADGM1304 part due to added SPI functionality, while still supporting existing applications. See attachment for datasheet change details.

Assembly site for select side by side LFCSP is moving from Amkor, Philippines (AP3) to existing qualified site ASE, Korea (AEK). Existing qualified BOM sets in AEK will be used

### Reason For Change:

Reason for re-design: Improved part performance, added SPI functionality and screening ability.

Reason for assembly site transfer: Amkor Philippines (AP3) issued discontinuance notice to ADI on the manufacture of select LFCSP side by side package (ADGM1304).

ADI's assembly subcontractors manufacture our products using Analog Devices specified manufacturing flows, materials, process controls and monitors. This assures that our customers receive the same level of quality and reliability on products they receive from different manufacturing locations.

#### Impact of the change (positive or negative) on fit, form, function & reliability:

This redesign and assembly site transfer will not affect the form, fit, quality or reliability of the ADGM1304 part. Qualified material set in AEK will be used.

Product Identification (this section will describe how to identify the changed material)

Changeover Material Date code is 1938

# **Summary of Supporting Information:**

Qualification has been performed per Industry Standard Test Methods. See attached Qualification Results Summary.

#### **Supporting Documents**

**Attachment 1: Type:** Qualification Results Summary

ADI\_PCN\_18\_0036\_Rev\_-\_Supporting Qualification Data ADGM1304 PCN.pdf

Attachment 2: Type: Qualification Results Summary

ADI PCN 18 0036 Rev - 000895 Qual Results Summary for Side-by-Side LFCSP at AEK.pdf

Attachment 3: Type: Datasheet Specification Comparison

Attachment 4: Type: Other

ADI\_PCN\_18\_0036\_Rev\_-\_BOM Set Comparison Amkor and ASE.pdf

For questions on this PCN.	please send an email to the regi	ional contacts below or contact v	your local ADI sales representatives.

Americas: Europe: Japan: Rest of Asia:

PCN\_Americas@analog.com PCN\_Europe@analog.com PCN\_Japan@analog.com PCN\_ROA@analog.com

Appendix A - Affected ADI Models					
Added Parts On This Revision - Product Family / Model Number (2)					
ADGM1304 / ADGM1304JCPZ-R2	ADGM1304/ADGM1304JCPZ-RL7				

Appendix B - Revision History					
Rev	Publish Date	Effectivity Date	Rev Description		
Rev	02-Oct-2019	04-Jan-2020	Initial Release		

Analog Devices, Inc.

Docld:4371 Parent Docld:4099 Layout Rev:7