

Eaton Electronics Division 5735 W. Las Positas Blvd #100 Pleasanton, CA 94588 www.eaton.com/electronics

Product Change Notice

PCN#: EE-PCN21026 11/11/2021

CLASSIFICATION OF CHANGE:

Packaging & Storage

DESCRIPTION OF CHANGE:

There has been a moisture sensitivity level improvement from 2a (4 weeks) to 1 (unlimited) for the parts listed on the second page of this PCN. Due to this improvement, moister barrier bag has been replaced with a polybag and the desiccant, humidity indicator and MSL label on the packaging have been removed.

REASON FOR CHANGE:

Continuous improvement - MSL improvement from 2a to 1 identified during annual design review.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

TIME SCHEDULE:

Effective immediately

ISSUED BY:

Jenan Krouchick Product Manager – Circuit Protection

CONTACT INFORMATION:

For questions or comments, please contact <u>https://www.eaton.com/content/eaton/us/en-us/products/electronic-components/contact-us.html</u>

PARTS AFFECTED:

Part Number	Previous MSL	Updated MSL
PTS080524V010	2a	1
PTS08059V020	2a	1
PTS08056V035	2a	1
PTS08056V050	2a	1
PTS08056V075	2a	1
PTS120660V005	2a	1
PTS120660V010	2a	1
PTS120630V012	2a	1
PTS120630V016	2a	1
PTS120624V020	2a	1
PTS120616V025	2a	1
PTS120616V035	2a	1
PTS12066V050	2a	1
PTS120615V050	2a	1
PTS12066V075	2a	1
PTS12066V100	2a	1
PTS12066V110	2a	1
PTS12066V150	2a	1
PTS12066V200	2a	1
PTS181230V010	2a	1
PTS181260V014	2a	1
PTS181230V020	2a	1
PTS181216V035	2a	1
PTS181216V050	2a	1
PTS181213V075	2a	1
PTS181224V075	2a	1
PTS181233V075	2a	1
PTS18128V110	2a	1
PTS181216V110	2a	1
PTS181224V110	2a	1
PTS18126V125	2a	1
PTS181216V125	2a	1
PTS18128V150	2a	1
PTS181212V150	2a	1
PTS181224V150	2a	1
PTS18128V160	2a	1
PTS18128V200	2a	1
PTS18126V260	2a	1
PTS18126V300	2a	1