



AMGIS

May 24, 2016

Digi-Key
701 Brooks Avenue South,
Thief River Falls, MN 56701 USA

Attn: Josh Knott

Subject: Process Change Notice

Dear Josh,

This is to give formal notice that some of the Amgis SWS parts are being discontinued effective immediately. This is due to the availability of the materials used in these products. Please see below list of part numbers being impacted and the replacement part numbers:

Discontinued part number	Replacement part number
SWS-0.20-374	SH150S-0.20-374
SWS-0.25-256	SH150S-0.25-256
SWS-0.30-176	SH150S-0.30-176
SWS-0.38-118	SH150S-0.38-118
SWS-0.46-78	SH150S-0.46-78
SWS-0.56-55	SH150S-0.56-55
SWS-0.68-39	SH150S-0.68-39
SWS-0.84-26	SH150S-0.84-26
SWS-1.02-17	SH150S-1.02-17
SWT-0.20-374	SH150T-0.20-374
SWT-0.25-256	SH150T-0.25-256
SWT-0.30-176	SH150T-0.30-176
SWT-0.38-118	SH150T-0.38-118
SWT-0.46-78	SH150T-0.46-78
SWT-0.56-55	SH150T-0.56-55
SWT-0.68-39	SH150T-0.68-39
SWT-0.84-26	SH150T-0.84-26
SWT-1.02-17	SH150T-1.02-17

10899 Kinghurst Street, Suite 220 – Houston, Texas 77099
Toll free (877)762-6447 – Phone (832)775-1319 – Fax (832)775-1317
E-Mail: sales@amgistoroids.com – www.amgistoroids.com



AMGISO

I checked and Digi-Key does not have stock of any of the part numbers being discontinued.

Please let me know if you have any questions.

Sincerely,

Jakob Jakobsson
Sales Manager