

## **Product Change Notification (PCN)**

PCN Number	510998	Date Issued	October 22, 2021
Reason for Change	Change Supplier		
Change Type Description	This letter is to inform you that Molex is adding a new supplier or the supplier is making a change affecting the part(s) identified in this notice. There will be no negative impact to product performance as a result of this change.		
Reason for Short Notice	Special Request		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports will be available after below listed date		
Internal Molex Qualification Date	October 25, 2021		
Sample Availability Date (Changed Part)	October 25, 2021		
Planned Implementation Date	October 31, 2021		
Method of Identifying Change	Date code After C	<b>SEE</b> hange	
	constrained LCP market orders. The Molex evalu- qualification necessary q Product In	used a global shortage for various grades of resin market, has causer identified as internal shortage of energin ng. Molex identified as internal shortage of resins re- refore, an atternative resin has been identified for i ate and select the same type atternative resin with action on new source material to ensure the same ualification and same type resin, Molex supposes i <b>typact</b> impact to fit, form, function <sup>*</sup> .	relative product. current resin material. Molex team will take necessary performance on Molex product. Considering the

Planned Implementation date.

 In order to ensure supply continuity. Molex will gradually start to use of new materials according to the sequence of verification completed. It is expected to gradually switch from October to December on different products.

## molex

**Product Change Notification (PCN)** 

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:510998**" in the e-mail Subject line for faster response.

## RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

PCN #	Molex Part #
510998	753100001
510998	754505001
510998	754545001
510998	754625001
510998	756405001
510998	760445001
510998	760445002
510998	760455001
510998	760465001
510998	760485001
510998	760905001
510998	760925001
510998	763527001
510998	1704320002
510998	2027180100

## Affected Parts:

75310-0001
76044-5001
76046-5001
76091-5001