



Date: 6/13/18

EOL Number 20180613001

To Whom It May Concern,

**Subject: Product Discontinuance**

Bel Fuse Inc. is issuing this correspondence as confirmation of planned discontinuance of below parts. Please remove the following Bel P/Ns from your AVL:

**EOL Parts**

|              |              |              |
|--------------|--------------|--------------|
| 0RLC-25T120G | 0RLC-10T240G | SRDC-16D33DG |
| VRBC-16F2ALG | 0RLC-25T033G | SRSB-40U05LG |
| SLDM-06D1ALG | 0RLC-25T050G | VRBA-06A2A0G |
| SLDM-06D1ALR | 0RLC-25T12LG | VRPB-10A12SG |
| 0RHB-C5T033G | 0RLC-25T150G | VRPC-10A33SG |
| 0RHB-C5T03LG | 0RLC-25T240G | VRXE-18AS10G |
| 0RLB-22B1A0G | 0RQB-C0U03LG | VRXE-20AS20G |
| 0RLC-10T033G | SRBC-16F2A0G | SLDM-06D1A0G |
| 0RLC-10T050G | SRBC-16F2ALG | SLDM-06D1A0R |
| 0RLC-10T120G | SRDC-16D18DG | SLDM-06D1ALR |

There are no LTBs or LTS for these parts. There is also no replacement at this time.

Thank you for your understanding in this matter. Should you have any questions, please contact your local Bel representative or contact me directly at 201-432-0463.

Sincerely,

Frederick Usma  
Regional Sales Manager – Northeast  
Bel Fuse Inc.

206 Van Vorst Street  
Jersey City, NJ  
07302 USA

T 201.432.0463  
[belfuse.com](http://belfuse.com)